




**Docket No.:** TSAR001US  
**Title:** Standardized Rotary Actuator  
**Inventor:** Delbert Tsar

REPLACEMENT PAGE

1/11



**FIG. 1**

**BEST AVAILABLE COPY**

2/11




FIG. 2

3/11

300





FIG. 3

4/11



5/11

500 




FIG. 5

6/11




FIG. 6

7/11

700 ➤




FIG. 7

8/11




FIG. 8



9/11




FIG. 9

10/11




FIG. 10





FIG. 11



11/11




FIG. 12

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**